






<http://hgr.io/r/hmw630nr>

TRIP UNIT Energy




















> Ir	<105% Ir	≥ 105% Ir	I > 112% Ir
PTA	PTA OFF	PTA ON	PTA ON PTA OUT ON
Ready	OFF		ON







:hager



5



3P
4P



3P
4P

